SD-DP-420
SD-DP-750
SD-DP-1150

Installation Instructions
◈ spacedec
Donut Pole | 420mm / 750mm / 1150mm

IMPORTANT INFORMATION

- **Each Quickshift Donut supports a maximum weight of 12kg (26½lbs)**
  - o Donut Pole 420mm supports a total of: 12kg (26½ lbs)
  - o Donut Pole 750mm supports a total of: 24kg (53 lbs)
  - o Donut Pole 1150mm supports a total of: 36kg (79½ lbs)
- This product suits VESA compliant displays with 75mm x 75mm and 100mm x 100mm mounting hole patterns.
- The manufacturer does not accept responsibility for incorrect installation.

Component Checklist

Check you have received all parts against this component checklist according to the product you have purchased.

Donut Pole 420mm (16½")

VESA plate (x1)
Quickshift Donut (x1)

OR

Donut Pole 750mm (29½")

VESA plate (x1)
Quickshift Donut (x1)

OR

Donut Pole 1150mm (45¼")

VESA plate (x1)
Quickshift Donut (x1)

Hardware

Item	Description
Tension Tool (x1)	
Base Casting (x1)	
Bolt Through Washer (x1)	
M8 x 30mm Screw (x1)	
Security Screw (x1)	
2mm Allen Key (x1)	

Cable Ball
SD-DP-420 (x2)
SD-DP-750 (x4)
SD-DP-1150 (x6)

Cable Clip
SD-DP-420 (x2)
SD-DP-750 (x4)
SD-DP-1150 (x6)

Mounting Screws
M4 x 10mm (x4)
M4 x 12mm (x4)
M4 x 16mm (x4)

Desk Clamp

Note: Only one Desk Clamp Box is included in every Donut Pole purchased.

- Desk Clamp Bracket (x1)
- Pressure Plate (x1)
- M8 Desk Clamp Screw (x1)
- 5mm Allen Key (x1)

TOOLS REQUIRED:
- Power Drill
- 10mm (³/₈") Drill Bit
- Phillips Head Screw Driver

Step 1. Mounting Options

There are two Mounting Options: **Bolt Through** and **Desk Clamp**
To use the **Bolt Through** system, (Suits desktop thicknesses of 12mm-40mm [¹/₂"-1¹/₂"]) follow the Bolt Through instructions at **Option A.**
To use the **Desk Clamp**, (Suits desktop thicknesses of 12mm-38mm [¹/₂"-1¹/₂"]) follow the Desk Clamp instructions at **Option B.**

Option A. Bolt Through

Drill a 10mm (³/₈") hole in the work surface at the desired position and assemble as shown.

NOTE: It is recommended that the pole assembly be mounted towards the rear edge of the work surface.


Ensure cable slot is facing the back
Pole Assembly
Base Casting
10mm (³/₈") hole
Work surface

Bolt Through Washer
M8 Desk Clamp Screw
5mm Allen Key
Tighten Firmly

Option B. Desk Clamp

Attach the Desk Clamp Bracket to the bottom of the Pole Assembly using the M8 x 30mm Screw. **Tighten Firmly** using the 5mm Allen Key. Ensure the Spacedec Logo on the Base Casting is facing the front as shown.

5mm Allen Key
Desk Clamp Bracket
M8 x 30mm Screw
Base Casting
Ensure cable slot is facing the back

Attach the Donut Pole Assembly using the Desk Clamp as shown.

Note: Desk Clamp suits 12mm (¹/₂") - 38mm (1¹/₂") thick work surfaces. Adjust the height of the Pressure Plate to suit your work surface.

M8 x 30mm Screw
Pressure Plate
Work surface
5mm Allen Key
Tighten Firmly

Step 2. Attach the VESA plate to your Display

There are two mounting hole configurations:
• 75 x 75mm
• 100 x 100mm

Choose appropriate Mounting Screws from the Hardware supplied to suit your Display.

Mounting Screws (x4)

VESA Plate

Top of Display

75mm

75mm

100mm

100mm

Back of Display

Step 3. Attach your Display to the Quickshift Donut

Hook the top of the VESA plate onto the Quickshift Mount.

VESA plate

Back of Display

Gently push the bottom of the Display into the Mount until you hear a 'CLICK'.

CLICK

Insert the Security Screw, and tighten using the 2mm Allen Key.

TIGHTEN

2mm Allen Key

## Step 4. Adjust the height of the Quickshift Donut

Open the lever to loosen the Quickshift Donut.

OPEN

Slide the Quickshift Donut to desired position.

If necessary, adjust the tension between the Donut and the Pole using the 5mm Allen key supplied.

TIGHTEN

LOOSEN

Close the lever to lock the Quickshift Donut in place.

CLOSE

Step 5. Adjust the VESA Ball Mount

Position your Display to the desired viewing angle, using the ±20° angular tilt allowed by the VESA Ball Mount. If the display does not hold its position, or is too resistant, adjust the Tension Plate (see diagram below).

To make any adjustments, use the Tension Tool supplied.

Tension Plate

Loosen (-kg)

Tightening Tool

Tighten (+kg)

Step 6. Cable Management

Connect cables to your Displays, routing them down the rear of the poles.

Push the cables into the slots, using either the Cable Balls or Cable Clips to secure them to the pole as shown.

Cable Clips

Cable Balls (x2)

Note: Ensure enough slack is left in cables to allow for movement. When the slot in each pole cannot be used, use the supplied Cable Clips to secure the display cables.

atdec